



Care and Maintenance

Annual Check

At least every 12 months, ensure all the mounting screws attaching desk/table tops, mechanisms are still working correctly.

Top Care

Tables, desks and workstations are supplied standard with melamine tops. Clean tops regularly by wiping them down with a damp cloth and a general purpose cleaner/detergent. For best results use streak free glass cleaner.

Stain and Mark Removal

- Stubborn marks or stains - apply Handy Andy or diluted Janola (1 part to 3 parts water), then wipe down with a warm damp cloth.
- Smearing, finger marks, marking from cold or hot dishes, stickiness - apply 1 or 2 applications of acetone (available at pharmacies) and wipe over with dry cloth.
- Felt pen or dry marker - use methylated spirits or acetone
- Paint - use acetone or thinners (from a paint shop)
- Glue - contact type - use Ados Solvent N (from a paint shop)

Follow on with streak free glass cleaner to remove any residues.

Frame Care

Keep the plastic and metal components of your table clean by wiping them down with a damp cloth and a general purpose cleaner/detergent. For best results use streak free glass cleaner.