

motionoffice

Expo Assembly Instructions



PARTS LIST:


- MOES (L&R Pairs)
- MOCS11 x 2
- MOSS11 x 4
- MLOOPS7B x 4
- MLOOPC60BO x 2

COMPONENTS LIST:

- 14 - Pins
- 1 - Allen Key




Expo Assembly Instructions




Recommended
2-person Step


To prevent possible scratches or damage, assemble the product on a soft surface such as a blanket, carpet or packaging.



Expo Assembly Instructions



- 1 Start with curved panel, insert Pins into keyholes, slide down until top is flush. Once panels are flush, slide pin on the underside of the panel across to lock panels together.



- 2 Place loop Ottomans as shown in this diagram from the inside outwards.